

Clamp meters

VE 340 A

Analog clamp meter to measure voltage (AC/DC), current (AC) and resistance.



- Analog clamp meter to measure alternating currents
- Data Hold function
- Power supply: 1 1.5 V battery
- Protection: 0.5 A diodes and fuse
- Operating temperature: 0 ÷ +50°C
- Operating humidity: < 75% RH (0 ÷ +35 °C)
< 65% RH (+35 °C ÷ +50 °C)
- Storage temperature: -20 °C ÷ +60 °C (<80% RH)
- Jaw opening: Ø 30 mm
- Weight: 290 g
- Included accessories: case, measurement points, instructions for use

| Code | Model | Description |
|----------|----------|--------------------------|
| VP029300 | VE 340 A | Analog clamp meter 300 A |

GENERAL CHARACTERISTICS

| Function | Capacity | Reading precision |
|------------|---------------------------------|------------------------|
| Voltage | DC 60 V | ± 3% of the full scale |
| Voltage | AC 150/300/600 V (50 ÷ 1000 Hz) | ± 3% of the full scale |
| Current | 6/60/300 A (50 ÷ 60 Hz) | ± 4% of the full scale |
| Resistance | Ω 1/10 kΩ | ± 4% of the full scale |

REFERENCE STANDARDS

Compliance with Community Directives: 2006/95/EC (Low Voltage) and 2004/108/EC (E.M.C.)
is declared with reference to the following standards: • Safety: EN 61010-1 / EN 61010-2-031 • E.M. Compatibility: EN 55014 / EN 61000-6-1